



Inspection Report Industrial

Report Reference:

Inspection #: 2022-CA-00262

- Used oil rag bins were available and in use.
- Good housekeeping throughout the facilities.
- There is a flammable storage cabinet on site.

Exit signs were posted.

I noted the following opportunities for improvement:

- The exit at the north-facing side of the building was obstructed with snow ice
- Access to the electrical panels was blocked.
- Loading dock of the new power plant has no protective guard or barricade.
- The fire extinguisher was not stored in a secure manner.

I issued directions as a result of this inspection. Procedures for informing the WSCC of compliance with the issued directions, or appealing one or more of those directions, can be found on the last pages of this report. The employer shall ensure the Record of Compliance (last page of the inspection report) is submitted to me on or before the assigned date.



Inspection Report Industrial

Report Reference:

Inspection #: 2022-CA-00262

Direction Number: 2022-CA-00262-003 **Status:** Open

Required Compliance Date: November 30, 2022

Observations: I observed that the electrical panel is obstructed and not easily accessible. Easy access to the electrical panel will minimize fire hazards and enhance emergency response when the need arises.

Direction: The employer shall comply with the following legislation

Legislation: Occupational Health and Safety Regulations(Northwest Territories)

Section 456: An employer shall ensure that electrical panels are (a) approved for their intended use and location; (b) protected from physical or mechanical damage; (c) readily accessible; and (d) fitted with an approved cover that has an approved filler in an unused opening.

