

NTPC Health & Safety Alert

Incident Summary – July 2020



Background

The following incidents were reported in July 2020. Medium and High Reasonable Potential for Harm (RPH) incidents are covered in more detail in separate alerts.

Practical Guidance

07-10-20, Fort Simpson, NTPC Incident, Low RPH

- Event: NTPC vehicle struck ferry ramp
- Response: Vehicle inspected, no damage

07-15-20, Colville Lake, NTPC Incident, Medium RPH

- Event: NTPC vehicle struck public vehicle while reversing out of driveway
- Response: Damage to rear of vehicle, to be repaired. Incident reported to RCMP

07-15-20, Fort Liard, NTPC Incident, Low RPH

- Event: Arm stuck while performing maintenance work
- Response: No injury, co-worker helped to free worker's arm

07-18-20, Fort McPherson, NTPC Incident, Low RPH

- Event: 100 L of glycol leaked from circulation pump seal, contained in plant
- Response: Spill cleaned up and reported

07-19-20, Inuvik, NTPC Incident, Low RPH

- Event: LNG gas alarm set off during offloading
- Response: Alarm investigated and reset

07-21-20, Fort Simpson, NTPC Incident, Low RPH

- Event: NTPC vehicle passenger side window cracked by rock while cutting grass
- Response: Window to be repaired, identify and remove potential hazards

during Tailboard
07-22-20, Yellowknife, Contractor Incident, Low RPH - Event: Contractors observed not following COVID-19 Safe Work Practices and safety rules - Response: Contractors provided with masks, Tailboard forms and site orientations
07-24-20, Tuktoyaktuk, NTPC Incident, Low RPH - Event: Marijuana odour noted inside crew trailer - Response: Reported to Manager, crew trailer cleaned
07-31-20, Taltson Hydro, Contractor Incident, Low RPH - Event: Sideview mirror struck with hard hat while exiting grader - Response: Tailboard revisited, Operators to put on bug nets after exiting equipment as not to obstruct view