





## Inspection Report Industrial

**Report Reference:**

Inspection #: 2022-SE-00107

- The Emergency Response Plan and Spill Response Plan were available
- High Voltage Danger warning signs were posted at the gate.
- Safety Data Sheets were available and up to date.
- Fire Emergency contact was posted.
- Spill kits including an oil waste can were available.

**I observed more positives than stated, and will be glad to share if requested.**

**I noted no opportunities for improvement at the time of the inspection.**

**I issued no directions as a result of this inspection.**

