



Inspection Report Industrial

Report Reference:

Inspection #: 2022-SE-00126

- The Emergency Response Plan and Spill Response Plan were available
- High Voltage Danger warning signs were posted at the gate.
- Safety Data Sheets were available and up to date.
- Fire Emergency contact was posted.
- Lock-out / Tag-out station was available.
- Spill kits including mats and oil waste containers were available.
- 1 flammable storage cabinet was available.

I observed more positives than stated, and will be glad to share if requested.

I noted the following opportunities for improvement at the time of the inspection:

- Fire emergency lights were not working.

I issued directions as a result of this inspection. Procedures for informing the WSSCC of compliance with the issued directions, or appealing of one or more of those directions, can be found on the last pages of this report. The employer must ensure the Record of Compliance (last page of inspection report) is submitted to me on or before the assigned date.



Inspection Report Industrial

Report Reference:
Inspection #: 2022-SE-00126

Record of Compliance

1. For each direction, once it is complied with, the Employer must:
 - a. Write in the actions taken towards complying with the direction given;
 - b. Initial the line; and
 - c. Fax or e-mail this page to the Safety Officer on or before the listed compliance date.
2. Once all directions are complied with, sign the Record of Compliance and fax or e-mail this page to the Safety Officer.

Direction Number	Compliance Required By	Compliance Status	Date	Initials
2022-SE-00126-001	December 30, 2022			

Verified by:

Employer Representative
(Print)

Signature