



Inspection Report Industrial

Report Reference:

Inspection #: 2022-SE-00154

- I observed that safe work practice was posted.
- I observed that Emergency Response Plan and Spill Response Plan were posted, and muster point location identified.
- High Voltage Danger warning signs were posted at the gate.
- Safety Data Sheets were available.
- Fire Emergency contact was posted.
- Lock-out / Tag-out station was available.
- Spill kits including mats and oil waste containers were available.
- I observed flammable storage cabinet was available.

I observed more positives than stated, and will be glad to share if requested.

I noted the following opportunities for improvement at the time of the inspection:

- I observed that some Safety Data Sheets were out-dated.
- I observed that the Plant Operator's supervisor regulatory familiarization training certificate has expired.

I issued directions as a result of this inspection. Procedures for informing the WSSCC of compliance with the issued directions, or appealing of one or more of those directions, can be found on the last pages of this report. The employer must ensure the Record of Compliance (last page of inspection report) is submitted to me on or before the assigned date.



Inspection Report Industrial

Report Reference:
Inspection #: 2022-SE-00154

Record of Compliance

1. For each direction, once it is complied with, the Employer must:
 - a. Write in the actions taken towards complying with the direction given;
 - b. Initial the line; and
 - c. Fax or e-mail this page to the Safety Officer on or before the listed compliance date.
2. Once all directions are complied with, sign the Record of Compliance and fax or e-mail this page to the Safety Officer.

Direction Number	Compliance Required By	Compliance Status	Date	Initials
2022-SE-00154-001	January 31, 2023			
2022-SE-00154-002	January 31, 2023			

Verified by:

Employer Representative
(Print)

Signature